


# 99PC-015 : PARE CHOC AVANT / FRONT BUMPER SNYPER 800



ITEM	QTY	PART NUMBER	RÉV.
1	1	03PC-015	
2	2	04PL-554	A
3	4	HB114-20X1ZBG2	
4	4	HLN1/4-20ZBG2	
5	2	CAP-PL-RD-1.5x0.083	

2013-08-13

**Les Fabrication TJD inc.**147, chemin des Raymond Rivière-du-Loup (Québec), G5R 5X9  
www.tjd.ca